
FIG. 1






FIG. 3




FIG. 4




FIG. 5




FIG. 6




FIG. 7





FIG. 8






FIG. 10





FIG. 11






FIG.13





FIG. 14






FIG.16




FIG. 17




FIG. 18




FIG. 19





FIG. 20



Takamatsu et al.
END STOP FOR SLIDE FASTENER AND SLIDE FASTENER HAVING THE SAME
Atty Dkt. No. 114208-037
Sheet 14 of 18

FIG. 21




FIG. 22




FIG. 23




FIG. 24




FIG. 25

Sheet 17 of 18




FIG. 26




FIG. 27




FIG. 28

